


■ 検査データ自動取込例

The screenshot shows the OpenOffice.org Calc interface. The spreadsheet has columns A through J and rows 1 through 22. Column D is labeled '日付' (Date) and column E is labeled '時間' (Time). The data in columns F through H represents numerical values. To the left of the spreadsheet, a technical drawing of a rectangular part is shown with three dimensions labeled ①, ②, and ③. Dimension ① is a horizontal arrow indicating width. Dimension ② is a vertical arrow indicating height. Dimension ③ is a vertical arrow indicating depth. The spreadsheet data is as follows:

Row	Date (D)	Time (E)	F	G	H
2	2009/02/02	08:00:00	9.000	29.020	31.985
3	2009/02/02	08:00:05	8.990	29.015	31.970
4	2009/02/02	08:00:10	8.990	29.030	31.965
5	2009/02/02	08:00:15	8.995	29.015	31.980
6	2009/02/02	08:00:20	8.970	29.025	31.975
7	2009/02/02	08:00:25	8.980	29.005	31.980
8	2009/02/02	08:00:30	8.975	29.015	31.965
9	2009/02/02	08:00:35	8.960	29.025	31.980
10	2009/02/02	08:00:40	8.955	29.010	31.975
11	2009/02/02	08:00:45	8.960	29.020	31.970
12	2009/02/02	08:00:50	8.975	29.015	31.980
13	2009/02/02	08:00:55	8.960	29.035	31.975
14	2009/02/02	08:01:00	8.950	29.010	31.985
15	2009/02/02	08:01:05	8.955	29.005	31.985
16	2009/02/02	08:01:10	8.970	29.025	31.980
17	2009/02/02	08:01:15	8.965	29.015	31.975
18	2009/02/02	08:01:20	8.955	29.020	31.965
19	2009/02/02	08:01:25	8.950	29.030	31.970
20	2009/02/02	08:01:30	8.960	29.015	31.975
21	2009/02/02	08:01:35	8.950	29.010	31.975
22	2009/02/02	08:01:40	8.955	29.005	31.980

■ 応用例

- ・ 寸法計測検査治具



■お問合せは



SYSTEM INTEGRATION FOR MANUFACTURING

エヌシー 株式会社

〒432-8065 静岡県浜松市南区高塚町1909(NCビル)

TEL(053)449-0159

FAX(053)448-9165

E-Mail nc@ncsys.co.jp

ホームページ <http://www.ncsys.co.jp/>

2009年03月09日作成